

ELEMENT 3"					
MANUFACTURER	DIMMER TYPE	PART NUMBER	FIXTURES PER DIMMER	MEASURED LIGHTING OUTPUT RANGE	COMMENTS
Crestron	Dimming Module	CLS-C6	Consult Dimmer Co.	100% - 13%	
Crestron	Dimming Module	CLS-C6EX	Consult Dimmer Co.	100% - 13%	
Crestron	Dimming Module	CLS-C6M	Consult Dimmer Co.	100% - 13%	
Crestron	Dimming Module	CLS-C6MEX	Consult Dimmer Co.	100% - 13%	
Crestron	Dimming Module	CLS-C6MRF	Consult Dimmer Co.	100% - 13%	
Crestron	Dimming Module	CLS-C6RF	Consult Dimmer Co.	100% - 13%	
Crestron	Dimming Module	CLS-EXP-DIM	Consult Dimmer Co.	100% - 17%	12% low-end on 277V
Crestron	Dimming Module	CLS-EXP-DIMU	Consult Dimmer Co.	N/A	Not recommended 120v, 100%-8% on 277v
Crestron	Dimming Module	CLW-DELVEX-277-P	Consult Dimmer Co.	100% - 5%	277v only
Crestron	Dimming Module	CLW-DELVEX-E	Consult Dimmer Co.	100% - 12%	
Crestron	Dimming Module	CLW-DELVEX-P	Consult Dimmer Co.	100% - 12%	
Crestron	Dimming Module	CLW-DIMEX-E	N/A	N/A	Not recommended- some flicker
Crestron	Dimming Module	CLW-DIMEX-P	N/A	N/A	Not recommended- some flicker
Crestron	Dimming Module	CLW-DIMSWEX-E	N/A	N/A	Not recommended- some flicker
Crestron	Dimming Module	CLW-DIMSWEX-P	N/A	N/A	Not recommended- some flicker
Crestron	Dimming Module	CLX-1DELV4	Consult Dimmer Co.	100% - 16%	
Crestron	Dimming Module	CLX-1DIM4	Consult Dimmer Co.	100% - 20%	May require firmware, consult Crestron
Crestron	Dimming Module	CLX-1DIM8	Consult Dimmer Co.	100% - 20%	May require firmware, consult Crestron
Crestron	Dimming Module	CLX-2DIM2	Consult Dimmer Co.	100% - 20%	May require firmware, consult Crestron
Crestron	Dimming Module	CLX-2DIM8	Consult Dimmer Co.	100% - 20%	May require firmware, consult Crestron
Crestron	Dimming Module	DIN-1DIM4	Consult Dimmer Co.	100% - 12%	100% - 8% ON 277V
Crestron	Dimming Module	DIN-1DIMU4	Consult Dimmer Co.	100% - 14%	
Crestron	Dimming Module	GLX-DIM6	Consult Dimmer Co.	100% - 5%	100% - 7% ON 277V
Crestron	Dimming Module	GLXX-2DIM8	Consult Dimmer Co.	100% - 6%	100% - 7% ON 277V
Crestron	Dimming Module	P-DIMEX	N/A	N/A	Not recommended- some flicker
Forbes & Lomax	Incandescent	600 Watt Incandescent	1 - 6	96% - 15%	Do not exceed load listed
Leviton	MLV	Model 6613	Not Recommended	Not Recommended	Limited dimming range, not recommended
Leviton	ELV	Model 6615	1 - 18	96% - 20%	
Leviton	Incandescent	Model 6633	1 - 7	96% - 3%	Single fixture will not power at lowest end of dimming range
Leviton	UNIV	Model 6672	1 - 12	96% - 25%	
Leviton	UNIV	Model 6674/IPL06	1 - 12	96% - 4%	
Leviton	ELV	Model IPE04	1 - 18	96% - 10%	
Leviton	Incandescent	Model IPI06	1 - 7	96% - 15%	
Leviton	MLV	Model IPM06	Not Recommended	Not Recommended	Limited dimming range, not recommended
Leviton	UNIV	Model IPSD6/IPVD6	Not Recommended	Not Recommended	Limited dimming range, not recommended
Leviton	Incandescent	Model VP106	1 - 7	96% - 6%	
Leviton	ELV	Model VPE04	1 - 18	96% - 18%	
Leviton	MLV	Model VPM06	1 - 12	96% - 5%	
Leviton	Incandescent	Model VR106	Not Recommended	Not Recommended	Limited dimming range, not recommended
Leviton	ELV	Model VRE04	1 - 18	96% - 10%	
Leviton	MLV	Model VRM10	1 - 12	96% - 5%	
Lutron	Incandescent	DV-600P-WH	1 - 3	98% - 1%	
Lutron	Incandescent	DVCL-153P-WH	Not Recommended	Not Recommended	Buzzing
Lutron	ELV	DVELV-303P	1 - 18	97% - 4%	
Lutron	ELV	HQRD-6NA	1-10	96%-2%	
Lutron	Dimming Module	HW/LP-RPM-4A-120	1 - 10	100% - 15%	High and low-end trim required
Lutron	Dimming Module	HW/LP-RPM-4U-120	1 - 10	100% - 13%	High and low-end trim required
Lutron	Incandescent	MA-600-WH	Not Recommended	Not Recommended	Flicker at low end
Lutron	ELV	MRF2-6ELV-120-WH	1 - 18	98% - 2%	
Lutron	ELV	NTELV-600-WH	1 - 18	98% - 8%	
Lutron	ELV	NVELV-600-WH	1 - 18	94% - 10%	
Lutron	ELV	SELV-600-WH	1 - 18	94% - 4%	
Vantage	Dimming Module	EDIMMOD	Min 1	96% - 10%	Consult dimmer company for max fixtures per dimmer. Recommend PWM, reverse phase.
Vantage	Dimming Module	RDR4	Min 2	100% - 2%	Consult dimmer company for max fixtures per dimmer. Recommend PWM, reverse phase.
Vantage	Dimming Module	SDM12-EM	Min 2	95% - 7%	Consult dimmer company for max fixtures per dimmer. Recommend PWM, reverse phase.

**ELEMENT 3" Hi Lume Driver- 2 wire dimming only\***

MANUFACTURER	DIMMER TYPE	PART NUMBER	FIXTURES PER DIMMER	MEASURED LIGHTING OUTPUT RANGE	COMMENTS
Lutron	GRAFIK Eye 3000	GRX-3100, GRX-3500	1-10 (per output)	100-1%	Set load type before adjusting low-end trim
Lutron	HomeWorks QS 1000W(LED)	HQRD-10ND	1-13	100-1%	Set load type before adjusting low-end trim
Lutron	HomeWorks QS adaptive dimmer	HQRD-6NA	1-8	100-1%	Set load type before adjusting low-end trim
Lutron	HomeWorks QS 600W (LED)	HQRD-6ND	1-8	100-1%	Set load type before adjusting low-end trim
Lutron	HomeWorks QS WPM (LED)	HQRJ-WPM-6D-120	1-10 (per output)	100-1%	Set load type before adjusting low-end trim
Lutron	HomeWorks 1000W dimmer	HRD-10ND, HWD-10ND	1-13	100-1%	
Lutron	HomeWorks 600W dimmer	HRD-6ND	1-8	100-1%	
Lutron	HomeWorks WPM	HWI-WPM-6D-120	1-10 (per output)	100-1%	
Lutron	RPM-4A module (LCP, HomeWorks, GRAFIK Systems, Quantum) (LED)	HW-RPM-4A-120 LP-RPM-4A-120	1-13 (per output)	100-1%	Set load type before adjusting low-end trim
Lutron	RPM-4U module (LCP, HomeWorks, GRAFIK Systems, Quantum) (LED)	HW-RPM-4U-120 LP-RPM-4U-120	1-10 (per output)	100-1%	Set load type before adjusting low-end trim
Lutron	Maestro Wireless	MRF2-6nd-120	1-8	100-1%	Do Not Use, Low Level Humming
Lutron	Nova T	NTLV-600-CPN0199	1-8	100-1%	
Lutron	GRAFIK Eye QS	QSGR, QSGRJ	1-10 (per output)	100-1%	Set load type before adjusting low-end trim
Lutron	RadioRA 1000W	RA-10ND	1-13	100-1%	
Lutron	RadioRA 600W	RA-6ND	1-8	100-1%	
Lutron	RadioRa 2 1000W	RRD-10ND	1-13	100-1%	
Lutron	Radio Ra 2 adaptive dimmer	RRD-6NA	1-8	100-1%	
Lutron	Stanza	SZ-6ND	1-8	100-1%	

\*NOTE: Two wire dimming only, not valid for 5 wire dimming. Contact Lutron tech support for deganging rules when using wallbox controls on the Hi-lume A-Series LED driver. Low-end trim may need to be adjusted to achieve 1% dimming. For information on low-end trim adjustment, consult installation instructions.

**ELEMENT 4"**

MANUFACTURER	DIMMER TYPE	PART NUMBER	FIXTURES PER DIMMER	MEASURED LIGHTING OUTPUT RANGE	COMMENTS
Lutron	Incandescent	DV-600P-WH	1 - 2	98% - 5%	
Lutron	ELV	DVCL-153P-WH	Not Recommended	Not Recommended	Buzzing
Lutron	ELV	DVELV-303P	1 - 12	95% - 10%	
Lutron	ELV	HQRD-6NA	1-10	96%-2%	
Lutron	Incandescent	MA-600-WH	Not Recommended	Not Recommended	Flicker at low end
Lutron	ELV	MRF2-6ELV-120-WH	1 - 12	96% - 2%	
Lutron	ELV	NTELV-600-WH	1 - 12	96% - 15%	
Lutron	ELV	NVELV-600-WH	1 - 12	94% - 20%	
Lutron	ELV	SELV-600-WH	1 - 12	94% - 10%	

**ELEMENT 6" LED Adjustable Retrofit**

MANUFACTURER	DIMMER TYPE	PART NUMBER	FIXTURES PER DIMMER	MEASURED LIGHTING OUTPUT RANGE	COMMENTS
Cooper	Incandescent	DAL06P	1-20	100% - 1%	Light flickers at low end of dimming.
Cooper	Incandescent	DLC03P	1-20	100% - 1%	Light flickers at low end of dimming.
Cooper	Incandescent	SLC03P	1-20	100% - 0%	Light flickers at low end of dimming.
Forbes & Lomax	Incandescent	FLR603P	4-20	100% - 7%	Light flickers at low end of dimming.
Legrand	Incandescent	H703PTVW	1-25	100% - 10%	Light flickers at low end of dimming.
Legrand	Incandescent	HCL453PW	1-25	100% - 12%	Light flickers at low end of dimming.
Leviton	Incandescent	6161	1-21	100% - 13%	Light flickers at low end of dimming.
Leviton	Incandescent	6631	1-25	100% - 0%	Light flickers at low end of dimming.
Leviton	Incandescent	6633-P	1-25	100% - 1%	Light flickers at low end of dimming.
Leviton	Incandescent	6673-10W	1-15	100% - 8%	Light flickers at low end of dimming.
Leviton	Incandescent	6683-IW	1-25	100% - 2%	Light flickers at low end of dimming.
Leviton	ELV	IPE04	1-16	100% - 4%	Recommended
Leviton	Incandescent	IPI06-1LZ	1-25	100% - 0%	Light flickers at low end of dimming.
Leviton	ELV	VPE06	1-25	100% - 6%	Recommended
Leviton	Incandescent	VPI06	Doesn't work	Doesn't work	Doesn't work
Lightolier	Incandescent	ZP260QEW	Consult Dimmer Co.	99%-4%	Light flickers at low end of dimming.
Lutron	Incandescent	AY-600P	1-26	100% - 12%	Light flickers at low end of dimming.
Lutron	Incandescent	CT103P	1-40	100% - 7%	Light flickers at low end of dimming.
Lutron	CL	CTCL-153P	1-10	98% - 25%	Low level flicker is better than incandescent dimmers but not as good as ELV.
Lutron	Incandescent	D-600P	1-25	99%-0%	Light flickers at low end of dimming.
Lutron	Incandescent	DV-600P	1-25	100% - 5%	Light flickers at low end of dimming.
Lutron	Incandescent	DVCL-153P	1-10	100% - 5%	Light flickers at low end of dimming.
Lutron	CL	DVCL-153P	1-10	98% - 17%	Low level flicker is better than incandescent dimmers but not as good as ELV.
Lutron	ELV	DVELV-300P	3-12	94% - 7%	Recommended
Lutron	ELV	DVELV-303P	3-12	94% - 7%	Recommended
Lutron	ELV	FAELV-500	3-21	100% - 8%	Recommended
Lutron	Incandescent	GL-600P	1-25	100% - 7%	Light flickers at low end of dimming.
Lutron	ELV	HQRD-6NA	3-25	97% - 1%	Recommended
Lutron	Incandescent	LG-600P	1-25	99% - 5%	Light flickers at low end of dimming.
Lutron	CL	LGCL-153P	1-10	97%-8%	Low level flicker is better than incandescent dimmers but not as good as ELV.
Lutron	Incandescent	MA-600	3-25	99% -2%	Light flickers at low end of dimming.
Lutron	CL	MACL-153M	1-10	94% - 9%	Low level flicker is better than incandescent dimmers but not as good as ELV.
Lutron	ELV	MAELV-600	3-25	100% - 1%	Recommended
Lutron	Incandescent	MAW-600	3-25	99% -2%	Light flickers at low end of dimming.
Lutron	Incandescent	MAW-600	3-25	99% -2%	Light flickers at low end of dimming.
Lutron	ELV	MRF2-6ELV-120	3-25	97% - 1%	Recommended
Lutron	ELV	NTELV-600	3-25	96-10%	Recommended
Lutron	ELV	NTELV-600	3-25	96-10%	Recommended
Lutron	ELV	RRD-6NA	1-25	98% - 1%	Recommended
Lutron	Incandescent	S600P	1-25	100% - 3%	Light flickers at low end of dimming.
Lutron	Incandescent	S600P	1-25	100% - 3%	Light flickers at low end of dimming.
Lutron	Incandescent	S-600P	1-25	98% - 8%	Light flickers at low end of dimming.
Lutron	Incandescent	S-603PG	3-25	86% - 6%	Light flickers at low end of dimming.
Lutron	CL	SCL-153P	1-10	99% - 6%	Low level flicker is better than incandescent dimmers but not as good as ELV.

Lutron	ELV	SELV-300P	3-12	93% - 7%	Recommended
Lutron	Incandescent	TG-600P	1-25	100% - 13%	Light flickers at low end of dimming.
Lutron	CL	TGCL-153P	1-10	98% - 1%	Low level flicker is better than incandescent dimmers but not as good as ELV.
Lutron	CL	TGCL-153P	1-10	98% - 1%	Low level flicker is better than incandescent dimmers but not as good as ELV.

### ELEMENT Reflections 12-inch

MANUFACTURER	DIMMER TYPE	PART NUMBER	FIXTURES PER DIMMER	MEASURED LIGHTING OUTPUT RANGE	COMMENTS
Forbes & Lomax	Triac	FLR603P	Consult Dimmer Co.	100-13%	
Insteon	ELV	2477D	Consult Dimmer Co.	100-20%	
Legrand	C*L	HCL45-3PW	Consult Dimmer Co.	100-16%	
Lutron	Triac	AY-600P-WH	Consult Dimmer Co.	100-18%	
Lutron	Triac	D-600P-WH	Consult Dimmer Co.	100-7%	
Lutron	C*L	DSL06-1LZ	Consult Dimmer Co.	100-10%	
Lutron	Triac	DV-600P	Consult Dimmer Co.	100-12%	
Lutron	C*L	DVCL-153P	Consult Dimmer Co.	100-2%	
Lutron	ELV	DVELV-300P	Consult Dimmer Co.	100-8%	
Lutron	Triac	GL-600P-WH	Consult Dimmer Co.	100-12%	
Lutron	ELV	HQRD-6NA	Consult Dimmer Co.	100-3%	
Lutron	Triac	MA-600-WH	Consult Dimmer Co.	100-5%	
Lutron	C*L	MACL-153M	Consult Dimmer Co.	100-10%	
Lutron	ELV	MAELV-600	Consult Dimmer Co.	100-3%	
Lutron	ELV	MRF-2-6ELV-120	Consult Dimmer Co.	100-3%	
Lutron	ELV	NTELV-500	Consult Dimmer Co.	100-12%	
Lutron	C*L	PD-6WCL	Consult Dimmer Co.	100-0.5%	
Lutron	ELV	RRD-6NA	Consult Dimmer Co.	100-3%	
Lutron	Triac	S-600P	Consult Dimmer Co.	100-13%	
Lutron	ELV	SELV-300P	Consult Dimmer Co.	100-8%	
Lutron	C*L	TGCL-153P	Consult Dimmer Co.	100-20%	slight flicker at dim

### ELEMENT Reflections 5-inch

MANUFACTURER	DIMMER TYPE	PART NUMBER	FIXTURES PER DIMMER	MEASURED LIGHTING OUTPUT RANGE	COMMENTS
Forbes & Lomax	Triac	FLR603P	Consult Dimmer Co.	100-12%	pop-on
Insteon	ELV	2477D	Consult Dimmer Co.	100-2%	
Legrand	C*L	HCL45-3PW	Consult Dimmer Co.	100-15%	pop-on
Lutron	Triac	AY-600P-WH	Consult Dimmer Co.	100-17%	
Lutron	Triac	D-600P-WH	Consult Dimmer Co.	100-3%	flicker below 3%
Lutron	C*L	DSL06-1LZ	Consult Dimmer Co.	100-8%	
Lutron	Triac	DV-600P	Consult Dimmer Co.	100-11%	
Lutron	C*L	DVCL-153P	Consult Dimmer Co.	100-1%	
Lutron	ELV	DVELV-300P	Consult Dimmer	100-7%	
Lutron	Triac	GL-600P-WH	Consult Dimmer Co.	100-11%	
Lutron	ELV	HQRD-6NA	Consult Dimmer Co.	100-2%	pop-on
Lutron	Triac	MA-600-WH	N/A	Flicker	Not recommended
Lutron	C*L	MACL-153M	Consult Dimmer Co.	100-10%	
Lutron	ELV	MAELV-600	Consult Dimmer Co.	100-2%	pop-on
Lutron	ELV	MRF-2-6ELV-120	Consult Dimmer Co.	100-2%	pop-on
Lutron	ELV	NTELV-500	Consult Dimmer Co.	100-12%	
Lutron	C*L	PD-6WCL	Consult Dimmer Co.	100-0.5%	
Lutron	ELV	RRD-6NA	Consult Dimmer Co.	100-2%	pop-on
Lutron	Triac	S-600P	Consult Dimmer Co.	100-13%	
Lutron	ELV	SELV-300P	Consult Dimmer Co.	100-7%	
Lutron	C*L	TGCL-153P	Consult Dimmer Co.	100-19%	

### ELEMENT Reflections 8-inch

MANUFACTURER	DIMMER TYPE	PART NUMBER	FIXTURES PER DIMMER	MEASURED LIGHTING OUTPUT RANGE	COMMENTS
Forbes & Lomax	Triac	FLR603P	Consult Dimmer Co.	100-14%	
Insteon	ELV	2477D	Consult Dimmer Co.	100-3%	
Legrand	C*L	HCL45-3PW	Consult Dimmer Co.	100-17%	pop-on
Lutron	Triac	AY-600P-WH	Consult Dimmer Co.	100-23%	
Lutron	Triac	D-600P-WH	Consult Dimmer Co.	100-4%	pop-on
Lutron	C*L	DSL06-1LZ	Consult Dimmer Co.	100-10%	
Lutron	Triac	DV-600P	Consult Dimmer Co.	100-13%	

Lutron	C*L	DVCL-153P	Consult Dimmer Co.	100-2%	flash on when turned on from dimmest level
Lutron	ELV	DVELV-300P	Consult Dimmer Co.	100-8%	
Lutron	Triac	GL-600P-WH	Consult Dimmer Co.	100-15%	
Lutron	ELV	HQRD-6NA	Consult Dimmer Co.	100-3%	
Lutron	Triac	MA-600-WH	Consult Dimmer Co.	100-6%	
Lutron	C*L	MACL-153M	Consult Dimmer Co.	100-12%	
Lutron	ELV	MAELV-600	Consult Dimmer Co.	100-3%	
Lutron	ELV	MRF-2-6ELV-120	Consult Dimmer Co.	100-3%	
Lutron	ELV	NTELV-500	Consult Dimmer Co.	100-13%	
Lutron	C*L	PD-6WCL	Consult Dimmer Co.	100-0.5%	
Lutron	ELV	RRD-6NA	Consult Dimmer Co.	100-3%	
Lutron	Triac	S-600P	Consult Dimmer Co.	100-16%	
Lutron	ELV	SELV-300P	Consult Dimmer Co.	100-9%	
Lutron	C*L	TGCL-153P	Consult Dimmer Co.	100-21%	